



Bay Networks

Part No. 306550-A Rev. 00

Technical Notice

When inserting an MCT1-1 or MCT1-2 link module into a chassis slot, make sure to align it properly. There is minimal clearance on these particular link modules, and improper installation may cause damage to a socketed framer device. This caution applies to the following boards:

Board Name	Part Number	Model Number
MCT1-1	105201	5944
MCT1-2	105207	5945